



POWERHOLD 5500

COVE BASE ADHESIVE

Powerhold 5500

DESCRIPTION:

Powerhold 5500 Cove Base Adhesive is a premium solvent-free adhesive with fast, aggressive wet suction to grip rubber and vinyl wall base. Powerhold 5500 can be used over most interior wall surfaces with the exception of vinyl wall covering and other similar non-porous surfaces that prevent the curing of any latex-based adhesive.

While the adhesive is designed to meet the challenges of poorly ventilated areas, sufficient air exchanges are still required to ensure proper curing of any latex-based adhesive.

Powerhold 5500 Adhesive is LEED compliant and is also compliant with South Coast Air Quality Management District Rule 1168.

DIRECTIONS:

1. Adhesive, wall base and job site must be conditioned at 65°F - 80°F for 48 hours before and after installation.
2. Use only on structurally sound surfaces, dry wall, concrete block, brick, plywood, paneling, masonry, plaster, etc.
3. Apply to surfaces that are clean, dry, and free from dust, wax and grease. Remove loose paint, plaster, old adhesive and other contaminants that would interfere with adhesion.
4. Cement or plaster must be thoroughly seasoned and dry.
5. With a 1/8" square or V-notched spreader, spread on back of base or wall surface.
6. Press base firmly into place immediately after application of adhesive.
7. Wrapped base or rolled base should lay flat for 24 hours before application.
8. For best results, it is recommended to wipe the back of rubber wall base with Mineral Spirits to remove residual mold release from manufacture.

DO NOT APPLY OVER NON-POROUS SURFACES SUCH AS MASONITE, PLASTIC LAMINATES OR VINYL WALL COVERINGS.

RECOMMENDED SUBSTRATES:

- Porous Concrete
- Properly Prepared Gypsum
- APA Approved Plywood
- Drywall
- Fully Cured Porous Masonry Walls

RESTRICTIONS:

1. For interior installations only.
2. Do not install when ambient temperature is not between 60°F & 95°F.
3. Do not install when ambient relative humidity is above 65%.
4. It is the sole responsibility of the installer to determine the suitability and compatibility of the adhesive for the user's intended use.

CLEAN-UP:

Remove wet adhesive immediately with a damp cloth. Use Powerhold 050 Cleaner or Mineral Spirits to remove dried adhesive. **CAUTION: Mineral Spirits are flammable. Read and follow all precautions on container label.**

PACKAGING:

- One 4 Gallon Pail
- 30 oz Tubes

WARRANTY:

Powerhold offers a limited warranty for this product when used in accordance with printed specifications. A copy of the limited warranty can be obtained by calling 844 638-4583(**GLUE**) or visiting www.powerhold.net.

COVERAGE:



Approximately 55-60 linear feet of 4" base per 30 oz tube.

Approximately 150-200 linear feet of 4" base per gallon.



POWERHOLD 5500 COVE BASE ADHESIVE

Powerhold 5500

| TROWEL | | ESTIMATED SPREAD RATE |
|---|--|---|
|  | | Approximately 150-200 linear feet of 4" base per gallon |
|  | | Approximately 150-200 linear feet of 4" base per gallon |

| Technical Data | |
|-------------------------|--------------------------------|
| Base Polymer | Acrylic Polymer |
| Color | Light Straw |
| Solids | 54-59% |
| VOC Content | <5 gram per liter |
| pH | 9.3 |
| Consistency | Paste |
| Trowelability | Light, Easy |
| Shelf Life | One Year in Unopened Container |
| Storage | 40°F-95°F |
| Application Temperature | 65°F-95°F (18°F-35°C) |
| Open Time | Up to 30 minutes |
| Freeze Thaw Stability | 5 Cycles @ 20°F |